

IMSAI ECO 77-0039

Affected products: CP-A Rev-4

Summary

Prevents the spurious one-shot triggering in RUN mode, causing unpredictable program execution.


This modification will disable one-shots (3 74123 Dual Monostable Multivibrators) during RUN.

Details

1. On the component side:
 - a. Cut the trace between U23 pin 11 and the load side of R60.
2. On the solder side:
 - a. Cut the trace between U17 pin 2 and via.
 - b. Cut the trace between U20 pin 11 and I19 pin 8.
 - c. Install a jumper between U20 pin 11 and U22 pin 6.
 - d. Install a jumper between U19 pin 8 and the load side of R60.
 - e. Install a jumper between U17 pin 2 and U17 pin 3.
3. Refer to the following diagrams for clarification.

Notes


IMSAI MFG. CORP. released this ECO on September 1, 1977



IMSAI SYSTEM
 CP-A REV. 4
 COMPONENT SIDE
 ECO 77-0098

SOLDER BRIDGE (MAY HAVE BEEN PREVIOUSLY IMPLEMENTED)

CUT



CIRCUIT SIDE

IMSAI SYSTEM
CP-A REV. 4
CIRCUIT SIDE
ECO 77-0098

Document Revision History

Revision	Date	Initial	Description
0	10/14/2024	NBB	Initial document creation.